


Check out our 10 step guide to MOT your conservatory and stop it leaking ...today!

CONSERVATORY REPAIRS



SLIPPED PANELS

ALUMINIUM TAPE SHOWING ON INSIDE AND SHEET VISIBLY DRIPPING ON OUTSIDE.



ROOF VENTS

POORLY FITTED VENTS CAN LEAK AND CAUSE THE ROOF PANEL TO SLIP.



MUNTIN BARS

FITTED DUE TO LIMITS IN GLASS UNIT SIZE. INCREASES THE LIKELIHOOD OF LEAKS.



RIDGE & RADIUS END

MOST EXPOSED PARTS OF THE ROOF. WRONG PARTS OR POOR FITTING CAN CAUSE PROBLEMS.



GUTTERS & VALLEYS

HOLDS RAINWATER. CAUSING CLIPS TO SNAP AND SEALS TO PERISH.



BOX GUTTER ADAPPTIONS

COMPLICATED JOINT IS PRONE TO PROBLEMS.



JACK SPARS

JOIN RIDGE OR EAVES TO HIP OR VALLEY SPARS. SUSCEPTIBLE TO LEAKS.

WE REPAIR

- 1 ✓ Repositioning slipped polycarbonate or glass units
- 2 ✓ Resolving conservatory roof leaks
- 3 ✓ Repositioning of glazing bar top cappings, drip bars and end caps
- 4 ✓ Re leading against property wall
- 5 ✓ Cleaning out and repairing guttering leaks
- 6 ✓ Adjusting conservatory doors
- 7 ✓ Replace misted units and gaskets
- 8 ✓ Roof vent leaks resolved
- 9 ✓ Muntin bars and boxed end adapters are also prone to leaking
- 10 ✓ Call us and stop that leak today!



FREE SURVEY | FREE QUOTES | FREE ADVICE

IPSWICH
01473 **288690**
www.falconwindows.com

